



December 2025

TO: Families and Staff Administration

FROM: VCLC

RE: Notification Letter Concerning Asbestos Content & Management Plan for the building in Syosset

In 1986, Congress passed the Asbestos Hazard Emergency Response Act. (AHERA). That law requires all schools, kindergarten through twelfth grade, be inspected and identify any asbestos-containing building materials. The law further requires the development of a Management Plan, based upon the findings of the inspection, which outlines our intent in controlling the potential for exposure to asbestos fibers in our schools.

In the past, asbestos was used extensively in building materials because of its insulating and fire retarding capabilities. Virtually any building built before the late 1970's contains at least some asbestos in pipe insulation, structural fireproofing, and floor tiles. Throughout the years, Variety has properly removed any asbestos containing materials that began to deteriorate or became damaged or disturbed during construction. In addition, we continually test the air quality and examine the remaining asbestos containing materials for damage and/or exposure in the Syosset building(s).

Our school has been inspected and some asbestos containing materials were identified in the building. The materials are distributed in various locations and include floor and wall tile, window caulking, and other mechanical areas not readily accessible to building occupants or students.

Your school's Inspection Report and Management Plan outlines in detail the methods used to maintain the materials in a safe manner. In addition, as required by law, appropriate school staff members have been trained to administer this program.

A copy of the inspection report and the management plan is on file in the Director of Facilities office for review if you so desire. If you have any questions, please contact Chris Milano at extension #2248.

Thank you.



Diciembre 2025

A: Familias y Personal de VCLC
DE: Administracion
RE: Carta de notificacion a cerca del Contenido de Amianto y el Plan de Gestion en el edificio en Syosset

En 1986, el Congreso aprobo la Ley de Respuesta a Emergencias a las Peligros de Asbesto (Asbestos Hazard Emergency Response Act). (AHERA). Esta ley requiere que todas las escuelas, jardin de infantes hasta el duodécimo grado, sean inspeccionadas e identificar materiales de construccion que contienen amianto (asbesto). La ley requiere aun mas el desarrollo de un Plan de Manejo, en base a las resultados de la inspeccion, que describe nuestra intencion en el control del potencial de exposicion a fibras de amianto en nuestras escuelas.

En el pasado, el amianto se utilizaba ampliamente en las materiales de construccion, debido a sus capacidades de aislamiento e ignifugas. Practicamente cualquier edificio construido antes de 1970, contiene al menos algo de amianto (asbesto) en el aislamiento de las tuberias, la proteccion estructural contra incendios y las baldosas del suelo. A lo largo de las arias, Variety ha eliminado adecuadamente cualquier material que contiene amianto (asbesto) que se haya comenzado a deteriorarse o que se haya dañado o perturbado durante la construccion. Ademas, proamos continuamente la calidad del aire y examinamos las materiales restantes que contienen amianto en busca de danos y / o exposicion en el edificio en Syosset.

Nuestra escuela ha sido inspeccionada y se han identificado algunos materiales que contienen amianto fen el edificio. Las fibras de amianto (asbesto) fueron encontradas en varios lugares e incluyen el piso, y azulejos, calafateo en algunas ventanas, y otras areas cuales no son facilmente accesibles a las ocupantes del edificio o estudiantes.

El Informe de la Inspeccion y Plan de Manejo esta descrito en detalles, las metodos utilizados para mantener las materiales de una manera segura. Ademas, tal coma lo requiere la ley, las miembros del personal apropiado de la escuela han sido entrenados para administrar este programa.

Una copia del informe de inspeccion y el plan de manejo se encuentra archivado en la Oficina del Director de Instalaciones para su revision si asi lo desea. Si tiene alguna pregunta, comuniquese con Chris Milano a la extension# 2131.

Gracias